

Q-356R1



SVE BULLETIN

SPECIAL VEHICLE ENGINEERING – BODY BUILDERS ADVISORY SERVICE

E-Mail via Website: www.FordBBAS.com (click "Contact Us")

Toll-free: (877) 840-4338

2023MY SUPER DUTY PICKUP BOX DELETE AND REMOVAL

REVISION	UPDATE	REVISION DATE
Q-356R1	Added content	15/ NOVEMBER/ 2022
Q-356	INITIAL RELEASE	09/ NOVEMBER / 2022

MODEL(S) AFFECTED:

2023MY SUPER DUTY PICKUPS

ISSUE / DESCRIPTION:

The Super Duty Pickup Box Delete option is not available for 2023 Model Year.

Pickup Box Removal is supported for 2023 Model Year Super Duty Pickups on the following models:

- F250 and F350
- All Body Styles, Wheelbases, GVWR, Engine and Drive combinations
- XL and XLT trim levels WITHOUT 360 Degree Camera and Blind Spot Information System (BLIS) features

The following packages contain the 360 Degree Camera and/or BLIS features, therefore vehicles with these options are **NOT SUPPORTED** for Pickup Box Removal:

- XL Trim
 - 17S - STX Appearance Package
 - 874 - 360 Degree Camera Package
 - 52T - Tow Technology Package
- XLT Trim
 - 17P - XLT Premium Package
 - 17K - Sport Appearance Package
 - 874 - 360 Degree Camera Package
 - 52T - Tow Technology Package

Please reference the 2023 Model Year Pickup Box Removal BBLB as it contains important technical information regarding box removal on Super Duty Pickups. It is available for view or download on the Ford BBAS website at: <https://www.fordbbas.com/publications>, under "Body Builder Layout Book".

The Super Duty BBLB also contains helpful information specific to Pickup Box Removal and is available at the same location within the BBAS site.

BBAS cannot provide support to eliminate error messages, warnings or MILs that are a result of removing the pickup box on vehicle configurations that are not supported for box removal.

Refer to the Body Builder Layout Book for additional guidelines and recommendations. If you have any questions, please contact the [Ford Body Builders Advisory Service](#) as shown in the header of this bulletin.